

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

of human services							_	
Day	рН	Alk	Phos	Sili	Y/N	< <have< td=""><td>County: Linn Agency: Linn</td></have<>	County: Linn Agency: Linn	
93	7.2	-				minimums	ENTRY POINT	
9/u	72					been met for		
95	73	,				this day?	EP-A	
9/6	74						PWS ID 4191707	
ala	7.3	· <del>-</del>				PLEASANT VALLEY ELEM SD #55		
910	7.3							
9/12	7.4	,				Sample period: September 2024  Month/Year		
9/13	7.4							
9/16	7.4							
917	7.5							
9/18	7.9					Number of excursions during this month:		
9/19	7.2							
9/20	7.2				<u> </u>			
9/23	7.1	,			<u> </u>			
9/20	7.2							
925	7.1				ļ	State.		
4/26	7.2		<u> </u>	ļ	<del> </del>	-Reference emailed 10/9/2024		
40	7.3				-	│ <i>⊢Ref</i> e	erence Comments	
4130	7.4		<u> </u>				Minimum Mateur Overlife	
		<u> </u>	-		<del> </del>	-	Minimum Water Quality Parameter(s) as set by State:	
			<del> </del>	<del>                                     </del>		-		
	<del> </del>	<u> </u>	<del>                                     </del>				pH 7.2	
<u> </u>	<del>                                     </del>	<del></del>	<del> </del>	-	<del> </del>	<del> </del>		
	<del> </del>			<del> </del>		-		
	-	ļ. <u>.                                   </u>		<u> </u>	-	1		
<b> </b> -	-				<u> </u>	-		
-	<del> </del>		<del>                                     </del>		<del> </del>	┨		
<u> </u>	<del>                                     </del>	<u> </u>			-	Print Name: Loni Weinman Signature: Jon M. William		
ļ	1		<del> </del>					
	<del>                                     </del>	<del> </del>	<del>  -</del>	<del>                                     </del>	-		-9-24	
L No =	J N = Fv	cursio	n) <b>Tot</b> a	l N'e	$\overline{\Box}$	<b>4</b>	Send to DWP within 10 days after end of	
140 -	14 — FX	Curaio	''/ I ULC	ai i <b>t 3</b>	0	sampling		
		ח	ים סר	inkin	م ۱۸/م	• •	O Box 14350 Portland OR 97293-0350	