

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Linn Agency: LINN COUNTY</th></have<>	County: Linn Agency: LINN COUNTY	
1						minimums	ENTRY POINT	
2						been met for	EP-A	
3						this day?		
4	Le.9					PWS ID 4191712 SEVEN OAK MIDDLE SCHOOL		
5	1.0							
6 7	7.0		-		_		1 2221	
8	7.0					Sample period:		
9							Month/Year	
10						Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the		
11	7.0							
12								
13								
14	7.0							
15						State.		
16								
17						Reference		
18	10							
19 20	1.0				_		Minimum Water Quality	
21	7.1					Parameter(s) as set by State:		
22	11				-		pH 7.2	
23								
24								
25	7.0							
26	7.0							
27						Print Na	mo:	
28	7.0					Print Name: Signature: Date & Phone#:		
$\rightarrow$	7. <mark>0</mark>							
30							DWP within 10 days after end of	
31 <b> </b>						sampling	<del>_</del>	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/