

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

1 2 3 4 5 6	7.2		
2 3 4	7.2		
3			
4			
5	7.2 7.2 7.2		
6	7.2		
7	7.2		
8	7.2		
9	7.2		
10 11 12			
11			
12	7.2 7.2 7.2		
13	7.2		
14	7.2		
15	7.2		
16			
17			
18			
19	7.2		
20			
21	7.2		
21 22	7.1		
23	7.2		
24			
25			
26	7.2		
27 (	7:1		
28			
29			
30			
31			

< <have< th=""><th>County: Linn Agency: LINN COUNTY</th></have<>	County: Linn Agency: LINN COUNTY				
minimums been met for	ENTRY POINT				
this day?	EP-A				
	PWS ID 4191712				
SEV	YEN OAK MIDDLE SCHOOL				
Sample period: April 21					
	Month/Year				

## Number of excursions during this month: \_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Refere	ence ———————————————————————————————————
	Minimum Water Quality Parameter(s) as set by State:
	pH 7.2
	2

Print Name: Paula Shoulders
Signature: Paula Shoulders
Date & Phone#:5/3/21 541.451.8454

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/