

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3	7.3				
4					
5					
6					
7					
8					
9	7.3				
10					
11					
12					
13					
14					
15					
16	7.2				
17					
18					
19					
20					
21					
22					
23	1.3				
24					
25					
26					
27					
28					
29					
30					
31					
lo = N	1 = Exc	ursion) Tota	l N's	

County: Linn	Agency: LINN COUNTY			
ENTRY POINT				
El	P-A			
PWS ID 4	1191712			
OAK MI	DDLE SCHOOL			
	g . 2021 Month/Year			
	ENTRY EI PWS ID 4 EN OAK MII iod: Au			

Number of excursions during this month: ____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minimum Water Quality Parameter(s) as set by \$	State
pH 7.2	
D. 1 9	1 7 2 2
nt Name: Paula Should	

Send to DWP within 10 days after end of sampling period

Date & Phone#: 9/3/2/ 54/45/-8454

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/