

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2	72				
4					
5					
6					
7					
8					
9					
10	7.2				
11					
12					
13					
14					
15					
16					
17					
18	7.3				
19					
20					
21					
22					
23					
24	7.3				
25					
26					
27					
28					
29					
30					
31					

< <have< th=""><th>County: Linn</th><th>Agency: LINN COUNTY</th></have<>	County: Linn	Agency: LINN COUNTY		
minimums	ENTRY POINT			
been met for this day?	EP-A			
	PWS ID 4	1191712		
SEV	EN OAK MI	DDLE SCHOOL		
Sample pe	eriod: <u>Jar</u>	1. 2022		
Month/Year				

Number of excursions during this month: ____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

-Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2
Print Name: Paula Shoulders
Signature:
Date & Phone#: 591. 101. 2906
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

awp.dmce@dhsoha.state.