

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3					
4					
5					
6	7.2				
7					
8					
9					
10					
11					
12	7.1				
13					
14					
15					
16					
17					
18					
19	7.2				
20					
21					
22					
23	7.2				
24					
25					
26					
27					
28					
29					
30					
31					

<< lave	County: Linn Agency: LINN COUNTY			
minimums	ENTRY POINT EP-A			
been met for this day?				
	PWS ID 4191712			
SEV	EN OAK MIDDLE SCHOOL			
	10 - 10000000 2110			
Sample pe				
	Month/Year			

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minimum Water Quality Parameter(s) as set by State:	
pH 7.2	
Dr. I. Starling	
Print Name: Paula Shoulders	_
Signature: Pull Shoulders	
Date & Phone#: 10 1 32 541 451 451)

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period

Reference -

dwp.dmce@dhsoha.state.or.us

Send to DWP within 10 days after end of