

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

1.2				
1.8				
1.2				
7.2				
1.2				
1.2				
7.8				
1.2				
7.2				
1.2				
1.2				
1.3				
1.2				
	1.2	1.2	1.2	1.2

< <have< th=""><th>County: Linn</th><th>Agency: LINN COUNTY</th></have<>	County: Linn	Agency: LINN COUNTY		
minimums been met for	ENTRY	ENTRY POINT		
this day?	El	P-A		
	PWS ID 4	1191712		
SEV	EN OAK MI	DDLE SCHOOL		
Sample pe	eriod: Jul	y >> Nonth/Year		

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality

Number of excursions during this month:

parameter(s) fall below the minimum set by the State.

	num Water Quality neter(s) as set by Sta
рН	7.2

Print Name: Paula Shoulders
Signature: Paula Shoulders
Date & Phone#: 541 · 451 · 8456

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

dwp.dmce@dhsoha.state.or.us