

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

| - | рН | Alk | Phos | Other | Y/1 |
|----|------------|--------|--------|-------|-----|
| 1 | 7.2 | | | | |
| 2 | 7.2 | | | | |
| 3 | 7.3 | | | | |
| 4 | | | | | |
| 5 | | | | | |
| 6 | | | | | |
| 7 | 1.2 | | | | |
| 8 | | | | | |
| 9 | | | | | |
| 10 | | | | | |
| 11 | | | | | |
| 12 | | | | | |
| 13 | 1.3 | | | | |
| 14 | 7.2 | | | | |
| 15 | 7.2 | | | | |
| 16 | 7.2 | | | | |
| 17 | | | | | |
| 18 | | | | | |
| 19 | | | | | |
| 20 | | | | | |
| 21 | 7.2 | | | | |
| 22 | 7.2 1.3 | | | | |
| 23 | | | | | |
| 24 | 7.2 | | | | |
| 25 | | | | | |
| 26 | | | | | |
| 27 | 1.2 | | | | |
| 28 | 7.2 | | | | |
| 29 | | | | | |
| 30 | | | | | |
| 31 | | | | | |
| 31 | I = Exc | ursion |)Total | N's | |

| < <have< th=""><th>County: Linn</th><th>Agency: LINN COUNTY</th></have<> | County: Linn | Agency: LINN COUNTY | | |
|--|--------------|---------------------|--|--|
| minimums been met for | ENTRY POINT | | | |
| this day? | EP-A | | | |
| | PWS ID 4 | 1191712 | | |
| SEV | EN OAK MI | DDLE SCHOOL | | |
| | <u> </u> | | | |
| Sample pe | riod: Feb. | 2023 | | |
| | / | Month/Year | | |

Number of excursions during this month: _

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

| Reference |
|---|
| Minimum Water Quality Parameter(s) as set by State: |
| pH 7.2 |
| |
| |
| |
| Print Name: Paula Shoulders |
| Signature: Paula Shoulders |
| Date & Phone#: 541.451.8456 |
| Send to DWP within 10 days after end of sampling period |

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/