

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day		Alk	Phos	Other	Y/N
1	7.2				
2 3					
3					
4					
5	1.2				
6					
7	7.2				
8	7.2				
9					
10					
11	7.7				
12	7.7 1.2 7.2				
13	7.2				
14	7.2				
15					
16					
17					
18	7.2				
19	7.Z				
20	7.2				
21	7.2				
21 22	7.2				
23					
24					
25	7.7				
26	7.7				
27	7.2				
28	7.2				
29	1.7				
30					
31					
10 = N	l = Exc	ursion	) Tota	l N's	

< <have< th=""><th>County: Linn Agency: LINN COUNTY</th><th></th></have<>	County: Linn Agency: LINN COUNTY	
minimums	<b>ENTRY POINT</b>	
been met for this day?	EP-A	
	PWS ID 4191712	
SEV	EN OAK MIDDLE SCHOOL	
Sample pe		
	Month/Year	

Number of excursions during this month: \_\_\_\_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

pH 7.2

Signature: Paula Shoulders

Date & Phone#: 541. 451. 8456

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/