

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Linn</th><th>Agency: LINN COUNTY</th></have<>	County: Linn	Agency: LINN COUNTY	
1						minimums	ENTRY	POINT	
2						been met for			
3	7.2					this day?	EP		
4							PWS ID 4	191712	
5	7.2					SEVEN OAK MIDDLE SCHOOL			
6	7.2								
7						Sample pe	eriod: OC	t. 2023	
8						Month/Year			
9	1.2								
10	7.2					Number of excursions during this month:			
11	7.2					(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the			
12	7.2	·							
13	7.2								
14						State.	rall below the h	ninimum set by the	
15 16	- 2					olato.			
17	7.2								
18	7.2					-Reference			
19	1.1							or Ouelity	
20	7.2				-	Minimum Water Quality Parameter(s) as set by State:			
21					-				
22					-	pH 7.2			
The second second	1.2				_				
24	7.2				_				
25	7.2								
26	7.2								
27	1.2					Drint No	ma: Paula	Shoulders	
28						Print Name: <u>Paula Shoulders</u> Signature: <u>Paula Shoulders</u> Date & Phone#: <u>193173 541.451.8456</u>			
29									
30	7.2					Send to DWP within 10 days after end of			
31	1.2					sampling		and a safer end of	
(No = N	(No = N = Excursion) Total N's								
OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350									

Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

dwp.dmce@dhsoha.state.or.u.