

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.2				
1 2 3					
3					
4	7.2				
5	7.2				
6					
7	7.2				
8	7.2				
9					
10					
11	7.2				
12	7.2				
13	7.2				
14	7.2				
15	7.2				
16					
17					
18	7.2				
19	7.2				
20	7.2				
21	7.2				
21 22	7.2				
23					
24					
25					
26	7.2				
27	7.2.				
28	7.7				
29	7.2				
30					
31					
10 = 1	1 = Exc	ursion) Tota	l N's	

< <have< th=""><th>County: Linn</th><th>Agency: LINN COUNTY</th></have<>	County: Linn	Agency: LINN COUNTY	
minimums	ENTRY POINT		
been met for this day?	El	P-A	
-	PWS ID 4	1191712	
SEV	EN OAK MI	DDLE SCHOOL	
		2022	
Sample pe	eriod: <u>De</u>	Month/Year	

Number of excursions during this month: ____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	mum Water Qu meter(s) as se	
рН	7.2	

Print Name: Paula Shoulders
Signature: Paula Shoulders
Date & Phone#: 541.8456

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/