

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1					
1 2 3 4	7.2				
3	7.2 7.2				
4	7.2				
5					
6					
7					
8	7.2				
9	7.2				
10	7.2 7.2				
11	7.2				
12	72				4
13					
14					
15					
16	7.2				
17					
18					
19	7.7				
20					
21					
22	7.2				
23	7.7				
24	7.2				
25	7.2				
26	7.2				
27					
28					
29	7.2				
30	7.2				
31	7.2				
1 = ol	l = Exc	cursion	) Tota	l N's	

< <have minimums<="" th=""><th colspan="2">County: Linn Agency: LINN COUNTY  ENTRY POINT</th></have>	County: Linn Agency: LINN COUNTY  ENTRY POINT	
been met for this day?	$\mathbf{E}$	P-A
	PWS ID	4191712
SEV	EN OAK MI	DDLE SCHOOL
Sample pe	riod:	Jan. 2024
		Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	Minimum Water Qu	
	Parameter(s) as se	et by State:
	pH 7.2	
Print Na	ame: Paula Shou	ulders
Print Na	ame: Paula Shoula Ire: Paula Shoul Phone#:2/1/24	ulders Iders

Send to DWP within 10 days after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period