

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.2				
3					
3					
4	7.2				
5	7.2				
6	7.2				
7	7.2				
8					
9					
10					
11	7.2				
12	7.2				
13	7.7				
14	7.2				
15					
16					
17					
18					
19	7.2				
20	7.2				
21	7.2				
22	7.2				
22 23					
24					
25					
26					
27	7.2				
28	7.2				
29	7.2				
30					
31					
lo = N	l = Exc	ursion) Total	N's	

< <have< th=""><th>County: Linn</th><th>Agency: LINN COUNTY</th></have<>	County: Linn	Agency: LINN COUNTY			
minimums	ENTRY POINT				
been met for this day?	EP-A				
	PWS ID	1191712			
SEV	EN OAK MI	DDLE SCHOOL			
Sample pe	riod: ma	urch 2024			
		Month/Year			

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	num Wa meter(s)		ality by State
рН	7.2]	

Print Name: Jaula Shoulders
Signature: Daula Shoulders

Date & Phone#: 541 451 845 4

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/