

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2	7.2				
3	7.2				
4	1.2				
5	7.2				
6					
7			i.c		
8	7.8				
9	7.2				
10	7.2				
11	7.2				
12	7.2				
13					
14					
15	7.2				
16	7.2				
17	1.2				
18	7.2				
19	7.2				
20					
21					
22	7.7				
23	7.2				
24	7.2				
25	7.2				
26					
27					
28					
29	7.2				
30	7.2				
31					
10 = 1	l = Exc	ursion)Tota	N's	

County: Linn	Agency: LINN COUNTY	
ENTRY POINT		
EP-A		
PWS ID 4	1191712	
EN OAK MI	DDLE SCHOOL	
eriod: Apri	1 2024	
	Month/Year	
	ENTRY EI PWS ID 4 VEN OAK MIT	

Number of excursions during this month: ____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

		ter Quality as set by St
рΗ	7.2	

Print Name: Paula Shoulders
Signature: Dalla Shoulders
Date & Phone#: 5/6/24 541.451.8456

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/