

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pН	Alk	Phos	Other Y	//N	< <have< th=""><th>County: Linn</th><th>Agency: LINN COUNTY</th></have<>	County: Linn	Agency: LINN COUNTY	
1	7.2	1				minimums	ENTRY	POINT	
2	7.2					been met for			
3	1.2					this day?	EP	'-A	
4							PWS ID 4	191712	
5						SEVEN OAK MIDDLE SCHOOL			
6	7.2								
7	7.2					Sample ne	ariod May	2024	
8	7.2					Sample period: <u>May</u> 2024 Month/Year			
9	7.2								
10	7.2					Number of excursions during this month:			
11						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality			
12									
13	7.2								
14	7.2					parameter(s) fall below the minimum set by the State			
15					_	State.			
16	7.2								
17						Reference			
18									
19						Minimum Water Quality Parameter(s) as set by State: pH 7.2			
20	7.2								
21	7.2								
22	7.2				_				
23	1.2				_				
24	7.2				_				
25									
26									
27	10					Print Name: <u>Paula Shoulders</u> Signature: <u>Daula Shoulders</u>			
28	7.2								
29	7.2					Date & Phone#: 4334 541.451.8456			
30 31	7.2				_	Send to	DWP within 10) days after end of	
						sampling	g period		
(NO = 1	No = N = Excursion) Total N's								
	OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350								

HA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

dwp.dmce@dhsoha.state.or.u.