

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
1 2 3 4					
3	7.2				
4	7.2				
5	7.2				
6	7.2				
7	7.2				
8					
9					
10	7.2				
11	7.2 7.2 7.2 7.3				
12	7.2				
13	7.2				
14	7.2				
15					
16					
17	7.2				
18	7.2				
19					
20	7.2				
21	7.2				
22					
23					
24	7.2				
25	7.2				
26	7.2				
27	7.2				
28	7.2				
29					
30					
31					

< <have< th=""><th>County: Linn</th><th>Agency: LINN COUNTY</th></have<>	County: Linn	Agency: LINN COUNTY
minimums been met for	ENTRY	POINT
this day?	El	P-A
	PWS ID 4	1191712
SEV	EN OAK MI	DDLE SCHOOL
Sample pe		me 2024 Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	num Water Quality meter(s) as set by State:
рН	7.2

Print Name: Paula Shoulders
Signature: Paula Shoulders
Date & Phone#: 7.3.24 541.570.2345

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/