

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.2				
2	7.2 7.2 7.2				
3	7.2				
4					
5	7.2				
6					
7					
8	7.2				
9	7.2				
10	7.2				
11	7.2				
12	7.2				
13					
14					
15					
16					
17	1.7	Y			
18	7.7				
19	7.7				
20					
21					
22	7.7				
23	7.2				
24	7.2				
25	7.2				
26					
27					
28					
29	1.2				
30	7.2				
31	7.2				
10 = N	I = Exc	ursion) Tota	l N's	

< <have< th=""><th>County: Linn Agency: LINN COUNTY</th></have<>	County: Linn Agency: LINN COUNTY
minimums	ENTRY POINT
been met for this day?	EP-A
	PWS ID 4191712
SEV	EN OAK MIDDLE SCHOOL
Sample pe	eriod: July 34 Month/Year

Number of excursions during this month: ____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	um Water Quality eter(s) as set by State
рН [7.2

Print Name: Paula Shoulders
Signature: Paula Shoulders
Date & Phone#: 7/31/24 541.451.8456

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/