

Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

Day	pН	Alk	Phos	Other	Y/N	< <h< th=""></h<>
1						mini
2	7.2					bee
3	7.2					this
4	7.2					-
5	7.2					
6	7.2					
7						
8						
9	7.2					
10	7.2					Nu
11	7.2					(0
12	7.2					Po
13	7.2					An
14						pa
15						Sta
16	7.2					
17	7.2					
18	7.1					
19	7.2					
20	7.2					
21						
22						
23	7.2					
24						
25						
26						
27						
28						
29						
30						
31						
No = N	I = Exc	ursion) Total	N's		

<have< th=""><th>Cou</th><th>nty: Linn</th><th>Agency: LINN COUNT</th><th>Y</th></have<>	Cou	nty: Linn	Agency: LINN COUNT	Y		
inimums een met for	ENTRY POINT					
is day?	EP-A					
	PW	S ID 4	191712			
SEV	EN O.	AK MII	DLE SCHOOI			
Sample pe	riod:					
		Month/Year				

Number of excursions during this month: _

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2
rint Name: Paula Shoulders
ignature: Dalla Shoulders
ate & Phone#: 12/31/24 541.451.8454

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/