

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <hav< th=""><th>е</th></hav<>	е
1						minimu	
2	7.2					been n	
3	7.2					this da	y?
4							-
5							SEV
6	7.2						
7	7.2					9.	ample per
8	1.2					Sample per	
9	7.2						
10	7.2					Num	ber of exc
11						(Ove	r 9 excursi
12							and Distri
13	7.2						xcursion' i
14	7.2					•	neter(s) fa
15	7.2					State	
16	7.2						
17	7.2						Referen
18							
19							Mi
20							Pa
21	7.7						
22	7.2						1
23	7.2						
24	1.7						
25							
26							
27	7.2						Print Nar
28	7.2						Signature
29	7.2						Date & P
30	7.2						Send to D
31	7.2						sampling
10 = N	I = Exc	ursion) Tota	l N's			29

ENTRY POINT

EP-A

PWS ID 4191712 EN OAK MIDDLE SCHOOL

Month/Year

Number of excursions during this month: _

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2

Print Name: Paula Shoulders
Signature: Paula Shoulders
Date & Phone#: 23 25 541.451.8456

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/