

### Water Quality Parameter Monitoring Form

# **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1					
1 2 3 4					
3	7.2				
4	7.2				
5					
6	なって				
7					
8					
9					
10	7.2				
11	7.2				
12					
13	7.2				
14	7.2				
15					
16					
17	7.2				
18	7.2				
19	7.2				
20	7.1				
21	7.2				
22					
23					
24	7.2				
25	7.2				
26	7.2				
27	7.2				
28	7.2				
29					
30					
31	7.2				
No = N = Excursion) Total N's					

<<Have minimums been met for this day?

County: Linn

Agency: LINN COUNTY

## **ENTRY POINT**

EP-A

### **PWS ID 4191712**

SEVEN OAK MIDDLE SCHOOL

Sample period: Month/Year

### Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

**Minimum Water Quality** Parameter(s) as set by State:

7.2 pH

Print Name: Paula Shoulders

Signature: Daula Shoulders

Date & Phone#: 541. 451.8456

Send to DWP within 10 days after end of

sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/