

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1	7.2				
2	7.2				
3					
4					
5					
6	7.2				
7	7.2				
8	7.2				
9	7.2				
10					
11					
12	7.2				
13					
14	7.2				
15					
16	7.2				
17					
18					
19	7.2				
20	7.2				
21					
22					
23					
24					
25					
26					
27	7.2				
28	7.2				
29	7.2				
30	7.2				
31					

<<Have
minimums
been met for
this day?

County: Linn Agency: LINN COUNTY

ENTRY POINT

EP-A

PWS ID 4191712

SEVEN OAK MIDDLE SCHOOL

Sample period: May 2025
Month/Year

Number of excursions during this month: _____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).
An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

**Minimum Water Quality
Parameter(s) as set by State:**

pH 7.2

Print Name: Paula Shoulders
Signature: Paula Shoulders
Date & Phone#: 541-451-8454 6/2/25

Send to DWP within 10 days after end of
sampling period

(No = N = Excursion) **Total N's** 0

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>