

Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1					
2	7.2				
3	7.2				
4	7.2				
5	7.2				
6	7.2				
7					
8					
9	7.2				
10	7.2				
11	7.2				
12	7.2				
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23	7.2				
24	7.2				
25					
26	7.2				
27	7.2				
28					
29					
30	7.2				
31					

<<Have
minimums
been met for
this day?

County: Linn

Agency: LINN COUNTY

ENTRY POINT

EP-A

PWS ID 4191712

SEVEN OAK MIDDLE SCHOOL

Sample period: June 2025
Month/Year

Number of excursions during this month: _____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).
An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

**Minimum Water Quality
Parameter(s) as set by State:**

pH 7.2

Print Name: Paula Shoulders
Signature: Paula Shoulders
Date & Phone#: 7/1/25 541.451.8456

Send to DWP within 10 days after end of
sampling period

(No = N = Excursion) **Total N's** 0

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>