

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	
1						
1 2 3 4						
3						
4						
5						
6						
7						
8						
9						
10						
11	7.2					
12						
13						
14						
15	7.2					
16						
17	7.2					
18	7.2					
19						
20						
21						
22	7.2					
23	7.2					
24						
25	7.2					
26						
27						
28						
29	7.2					
30	7.2					
31						
1 = oV	No = N = Excursion) Total N's					

< <have< th=""><th>County: Linn Agency: LINN COUNTY</th></have<>	County: Linn Agency: LINN COUNTY			
minimums	ENTRY POINT			
been met for this day?	EP-A			
	PWS ID 4191712			
SEVEN OAK MIDDLE SCHOOL				
Sample period: Sept. 25				
	Month/Year			

Number of excursions during this month: _

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2
Print Name: Paula Shoulders
Print Name: Paula Shoulders Signature: PShoulders Date & Phone#: 541.451.8456 10/1/25
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/