

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location	рН	Alk	PO4	other	Y/N	<has sample<="" th=""></has>
							met the DISTRIBUTION minimums?
							PWS ID: 41 9 1 8 10
	Da Kr.						
	· .				ė.). (System Name: FERN RIOKE MINDLE SCITA
3/7		8.5	2:			Y	
3/14		8.5				Y	
3/21		8-5				Y	
3/23		8.5		î- -	i Marian	Υ	
	* '-5	20.			0		
				¥ = 1			
		10 10	I.			100	
	Tar tarific A	<u> </u>	1.41				
							Note: Entry Point and Distribution Excursions are cumulative. Add Entry
				e	· ·		Point and Distribution Excursions to get
							total for sample period.
		-			*** ***		
			200	5. j	6	* 1	For OHA use only
					1		Minimum Water Quality
					e		Parameters as set by pH 7.8 Alk (Alkalinity) PO4 (Orthophosphate)
	Water State of the		-				
		-			-		
		21.3					
							Other (
						100 7	Print Name: JEFT THIRSTEN
	· · · · · · · · · · · · · · · · · · ·						Signature:

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/