

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ау	рН	Temp	chlas	Other	Y/N
1	7.9	60	1.3		
1 2 3			,		
	7.7	61	1.3		
4					
5 6					
6					
7					
8					
9	7.8	64	114		
10 11			,		
11	719	64	1.4		
12	/		,		
13					
14					
15	7.7	64	1.3		
6					
17	フラ	66	1.4		
18	, ,				
19					
20					
21					
22					
23	7.7	66	1.3		
24					
25	7.8	65	1.3		
26					
27					
28					
29]	
30					
31					
= N = Excursion) Total N's					

<<Have minimums been met for this day?

County: Lincoln

Agency: LINCOLN COUNTY

ENTRY POINT

EP-B

PWS ID 4192040

EDDYVILLE CHARTER SCHOOL

Sample period:

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

Minimum Water Quality Parameter(s) as set by State:

pH 7.2

Print Name:

Signature: 2

Date & Phone#: 10

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/