

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3	8.71	38			N
4					
5					
6					
7					
8					
9	8.5	43			N
10					
11					
12					
13					
14					
15					
16					
17					
18	7.8	35			N
19					
20					
21					
22					
23					
24					
25	8.1	31			N
26		- 31			
27					
28					
29	7.5	55			N
30					
31					
lo = N = Excursion) <b>Total N's</b>					0

< <have< th=""><th>County: Marion Agency: MARION COUNTY</th></have<>	County: Marion Agency: MARION COUNTY
minimums been met for	<b>ENTRY POINT</b>
this day?	EP-A
	PWS ID 4193768
	ABIQUA SCHOOL
	$\frac{1}{2}$
Sample pe	riod: Jan / 23

Number of excursions during this month: \_\_\_\_\_\_\_\_\_\_

Month/Year

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2 Alk 30.0 (Alkalinity)
Print Name: Single Sancepo
Signature:
Send to DWP within 10 days after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period