

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3					
4					
5					
6					
7	7.32	33			N
8					
9					
10					
11					
12					
13	8.9	31			N
14					
15				1	
16					
17					
18					
19					
20	9.	34			N
21			(a		
22					
23					
24					
25					
26					
27	9.31	44			N
28					
29		_/			
30					
31					
lo = N = Excursion) <b>Total N's</b>					0

<<Have
minimums
been met for
this day?</pre>

County: Marion Agency

Agency: MARION COUNTY

**ENTRY POINT** 

EP-A

PWS ID 4193768

ABIQUA SCHOOL

Sample period: Ftb

Month/Year

Number of excursions during this month: \_\_\_\_\_\_\_\_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Refe	rence	•	
			ater Quality as set by State:
	pH Alk	7.2	(Alkalinity)

Print Name: _	Show Samesoo
Signature:	Lyin Sul
Data & Dhane	4. 17 -1.1. 12

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/