

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	816	54			N
3					
3					
4					
5					
6	8,9	59			N
7					
8					
9					
10					
11					
12					
13					
14	8.2	60			N
15				20000	
16					
17					
18					
19					
20					
21					
22	9.2	54			N
23					
24					
25					
26					
27	4.3	76			N
28					4
29					
30					
31					
lo = N	V = Exc	ursion) Tota	I N'e	A

lo = N = Excursion) **Total N's**

W	< <ha< th=""><th>ve</th><th></th></ha<>	ve	
ľ	ninim	nums	3
k	peen	met	for
1	his d	ay?	

County: Marion Agency: MARION COUNTY

ENTRY POINT

EP-A

PWS ID 4193768
ABIQUA SCHOOL

Sample period: Mar 23

Month/Year

Number of excursions during this month: ___

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

inimu		ter Quality as set by State:
рН [7.2	(Alkalinity)

Print Name: Show Sange 00	
Signature: Muskuk	
Date & Phone#: NT MAC 23	

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/