

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3				•	
4					11
5					
6					(
7	7.3	5M			N
8					
9					
10					
11					
12					
13					
14					
15					
16	7.9	49			N
17					
18					
19					
20					
21					
22					
23					
24	1.7	38			N
25			,		
26					
27	-				
28					
29	7.6	40			7
30		·			
31					
lo = N = Excursion) Total Nie					~4

<<Have minimums been met for this day?

County: Marion Agency: MARION COUNTY **ENTRY POINT**

EP-A

PWS ID 4193768 ABIQUA SCHOOL

Sample period: 16

Number of excursions during this month: _Ø

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2 Alk 30.0 (Alkalinity)

Print Name: Shaw Signature: ____ Date & Phone#: 24 Fin 24

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/