

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <f< th=""><th>lave</th><th>County: Clackamas Count</th></f<>	lave	County: Clackamas Count	
		0			esopounicus	min	imums ·	ENTRY POINT	
							n met for		
					1/	this	day?	EP-A	
6	7,1				Y			PWS ID 4193970	
18	7.2			,	Y				
30	/0/.				Y_	CARUS ELEMENTARY			
							4	1	
					<u> </u>		Sample period: August 2021 Month/Year		
								· Month/Year	
			ļ					•	
	· .							during this month.	
							Number of excursions during this month:		
						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.			
			<u> </u>						
1,0		<u> </u>							
			-						
		•							
							⊢ <i>Refe</i>	erence ———————————————————————————————————	
				<u> </u>				Mr. Town Mr. Orrollity	
					<u> </u>			Winimum Water Quality Parameter(s) set for this PWS:	
			-		<u> </u>			-arameter (3) 30t for time i mor	
								pH 7.1	
								DECEIVEN	
								SEP 1 0 2021	
								Data Mgmt & Compliance	
								Drinking Water Program	
						Print Name: localini R. fyshe for Signature:			
				•			Date: 8		
					·	1.			
(No =	(No = N = Excursion) Total N's O Send to DWP within 10 days after end of sampling period								
	DHS Drinking Water Program, PO Box 14350, Portland, OR 97293-0350								

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp