

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <ha< th=""><th>ve</th><th>County: Clackamas Agency: CLACKAMAS COUNTY</th></ha<>	ve	County: Clackamas Agency: CLACKAMAS COUNTY	
1	7.4			HOC		minim		ENTRY POINT	
2							met for	2000 - 2	
3						this d	ay?	EP-A	
4							,	PWS ID 4194670	
5						OREGON TRAIL SD - BORING MID SCH			
6					<b>—</b> ].				
7						Sample period: Month/Year			
8									
9								Green, real	
10						Number of excursions during this month:			
11						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum			
12									
13									
14					-				
15	7,5			HOC		set b	y the Stat	e.	
16									
17							<i>⊢Referer</i>	nce —	
18									
19							M	inimum Water Quality	
20							Pa	arameter(s) as set by State:	
21	.							pH 7:2	
22									
23									
24							•		
25						•			
26									
27							Print Nan	ne: Malsea Lincoln Lane	
28							Signature	e: Mala	
29				•			Date & Pl	hone#: 09/9/24 503668-644	
30							Send to D	WP within 10 days after end of	
31							sampling	· ·	
o = N	= Excu	rsion) '	Total	N's	0				

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/