

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	/ pH	Alk	Phos	Other	Y/N	< <hav< th=""><th>ve l</th><th>County: Clackamas Agency: CLACKAMAS COUNTY</th></hav<>	ve l	County: Clackamas Agency: CLACKAMAS COUNTY		
1		•				minim	ums	ENTRY POINT		
2	7.5			15°C			met for	EP-A		
3						this da	ay?			
4								PWS ID 4194670		
5							OREGO	N TRAIL SD - BORING MID SCH		
6										
7						Sample period: September 24 Month/Year				
8								Month/Year		
9						L				
10						Number of excursions during this month:				
11						(Ove	(Over 9 excursions in 6 months is a violation.			
12						Entry Point and Distribution excursions are				
13								n 'excursion' is any day in which the		
14							r quality pa y the State	arameter(s) fall below the minimum		
15						Sel D	y ine stati	z.		
16	7.3			17°C	_					
. 17						Reference				
18										
19								inimum Water Quality		
20					-		Pa	arameter(s) as set by State:		
21								pH 7:2		
22						920				
23										
24								22"		
25						•				
26			-							
27					_		Print Nan	ne: Melsga Lane		
28			-		-	Signature:				
29	w 2						Date & Pl	none#: <u>18/09/24 503 668-644</u> 2		
30	7.3		/	7°C	\dashv	18	Send to D	WP within 10 days after end of		
31	sampling period sampling period									
N = 0	I = Excu	rsion)	Total	N's			*			

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/