## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control Temp

		r	T	T					
Day	pH	Alk	Phos	Other	Y/N	. < <hav< td=""><td>re</td><td>County: Clackamas Agency: CLACKAMAS COUNTY</td></hav<>	re	County: Clackamas Agency: CLACKAMAS COUNTY	
1						minim		ENTRY POINT	
2							net for	EP-A	
3						this da	ıy?		
4							*	PWS ID 4194670	
5							OREGO	N TRAIL SD - BORING MID SCH	
6						.			
7						Sample period: November 2024			
8								Month/Year	
9								m/	
10						Number of excursions during this month:			
11	7.3			17°C		(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.			
12	.								
13									
14									
15						Set D	y III <del>e</del> Sia	ie.	
16								*	
17							_Refere	nce	
18									
19								(linimum Water Quality	
20							F	arameter(s) as set by State:	
21								pH 7:2	
22							-		
23									
24	- 1				$\dashv$				
25   26	7.4	<del> .</del>	· /	rc					
27		-+			$\dashv$	Į			
28					$\dashv$		Print Na	8.76	
29				-	$\dashv$		Signatur	1.67	
30				-			Date & P	Phone#: /1/6/2024 503 668 64	
31				· +	-			OWP within 10 days after end of	
		reion).	Tat-!	NUC I		:	sampling	period	
U = 1V	= N = Excursion) Total N's						*		

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/