

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <hav< th=""><th>IΩ</th><th>County: Clackamas Agency: CLACKAMAS COUNTY</th></hav<>	IΩ	County: Clackamas Agency: CLACKAMAS COUNTY	
1						minim		ENTRY POINT	
2		 				- 10 15 15 10 0 10 1 10 10 10 10 10 10 10 10 10 10	met for		
3						this da	ay?	EP-A	
4								PWS ID 4194670	
5						OREGON TRAIL SD - BORING MID SCH			
6									
7							amnla ne	riod: May 2025	
8						/ Month/Year			
9						L			
10						Num	ber of ex	cursions during this month: Ø	
11						(Ove	r 9 excurs	ions in 6 months is a violation.	
12	7.5	120		17.10	-	Entry Point and Distribution excursions are			
13				·				n 'excursion' is any day in which the	
14								arameter(s) fall below the minimum	
15						set b	y the State	9.	
16							•		
17							Referen	ice	
18									
19							The same of the sa	inimum Water Quality	
20							Pa	arameter(s) as set by State:	
21								oH 7:2	
22						·			
23					_		-		
24						*			
25						*			
	1.5	120		16°C	_				
27					_		Print Nan	ne: Chelsea Lincoln Lane	
28							Signature	: Chalos	
29					_		Date & Ph	none#2 <u>6/4/25</u> 503-668-6442	
30					_		Send to D	WP within 10 days after end of	
31					_		sampling p		
= N =	= Excu	ırsion)	Total	N's	8			wi	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/