## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control Tomp

Day	pН	Alk	Phos	Other	Y/N	. < <hav< th=""><th>0</th><th>County: Clackamas Agency: CLACKAMAS COUNTY</th></hav<>	0	County: Clackamas Agency: CLACKAMAS COUNTY		
	PII					minimu		ENTRY POINT		
1				-		been r				
2						this da	11	EP-A		
3						-		PWS ID 4194670		
4						OREGON TRAIL SD - BORING MID SCH				
5							Olthoo			
6 7		W.				Date 1 2025				
-						S	sample period: <u>Chober 2025</u> Month/Year			
9								MOUNTER		
		ina		1270	1/	Num	her of ex	cursions during this month: 🙇		
10	7.4	120			7					
12 13 14 15						(Ove	(Over 9 excursions in 6 months is a violation.  Entry Point and Distribution excursions are			
						cumulative) An 'excursion' is any day in which the				
	-	-				water quality parameter(s) fall below the minimum set by the State.				
				-,						
16   17							⊢ Referei	nco -		
18 19 20 21 22 23							Helelel	nice .		
							IV.	Iinimum Water Quality		
						iy	Parameter(s) as set by State:			
								[ = 5 ]		
	*	-						pH		
						100				
	10	100		180	1/		- GR	*		
25	7.3	120		10	/	5. (i				
26	×		.				1 × ×	× 93		
27	47						Drint No.	me: Chelsea Lincoln Lane		
28										
29							Signatur			
30								1.0.1.9.1./		
31			3.4			à .		DWP within 10 days after end of		
		uroion	Total	NIA	7		sampling	penod		

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/