

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ķ	ID#	:	Sample Location	рН	Alk	P04	Other	Y/N	<has sample<="" th=""><th>County:</th><th>Agency: CLACKAMA</th></has>	County:	Agency: CLACKAMA	
									met the	Clackamas		
•	4/1/4	34	West Hall BF				160	_	minimum(s)?	DISTRI	BUTION	
1	1/2	4	Room15	7.3	ļ		1600					
	_	-	,	-					PWS ID 4194670			
	-	-		-					OREGON T	RAIL SD - B	ORING MID	
2/	1-1-	./		1/			~ 0			SCH		
24	15/2	4	West Hall BF	7,4			180		Sample Perio	d: 4/20	24	
7.	5/8	7	KOOM 15	1.5			10 0	-	Sample Period: 4/2044 Month/Year Sample Frequency: Every 12 months			
			2						Distribution Samples required: 1			
4	09/2	4	West Hau BF	7.4			180		Number of exc	cursions du	ıring this	
4/	29/2	,	Room 15	7.4			1900		Sample Period =			
									(Number of locations when any WQP was less than the minimum.) Note: Entry Point and Distribution Excursions are cumulative. Add Entry			
			4									
						-			Point and Distr			
						_			total for sample			
									Reference			
			· .	-+		_		_				
				-+			-	\dashv	14004	n Water Qua	•	
ł				-+					Paramete	ers as set b	y State:	
f							\dashv		pH 7.2			
.				-			-	-				
t	_				_	\neg	\dashv	\dashv				
İ	-						•					
		(N = No = Excursion) Total N's							Print Name: Chelsea Lincoln Lene			
Date:												
		Send to Drinking Water Program within 10 days after end of sampling period:										

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/