

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

< <have county:<="" th=""><th>Y/N</th><th>Other</th><th>Phos</th><th>Alk</th><th>рН</th><th>Day</th></have>	Y/N	Other	Phos	Alk	рН	Day
minimums EN'						1
been met for						2
this day?						3
PWS				,		4
COLUM						5
						6
Sample period: 🌽						7
Sample period.	Y				7.60	8
						9
Number of excursion						10
(Over 9 excursions in						11
Entry Point and Distrib						12
cumulative). An 'excu						13
water quality paramete						14
set by the State.	Y				7.70	15
						16
Reference —						17
						18
Minimum						19
Paramete						20
pH 7						21
						22
						23
						24
						25 26
						27
Print Name:	1/				7.70	28
Signature:	7				1.10	29
Date & Phone#:						30
Send to DWP wi						31
sampling period		I NI'c) Tota	Lureior	N = Exc	
	0	1115	ı) i Ota	Jul 3101	v — ⊏X(40 - I

< <have< td=""><td>County: Columbia Agency: COLUMBIA COUNTY</td></have<>	County: Columbia Agency: COLUMBIA COUNTY							
minimums	ENTRY POINT							
been met for this day?	EP-A							
PWS ID 4194717								
COLUMBIA RIVER PUD								
Sample period: April 2021								
Month/Year								

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minimum Water Quality Parameter(s) as set by State:
pH 7.2
Print Name: True Amari Ens

Print Name: Tim LAMMERS
Signature:
Date & Phone#: <u>4-28-2/ 2 503-397-</u> 8155
Send to DWP within 10 days after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/