

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1			The state of the s		
2					
2 3 4					
4	7.70				γ
5 6	7.69				Y Y Y
6	7,71				Y
7					
8					
9					
10					
11	7.69				Y
12					
13	7.70				Y
14	7.76			·	Y
15					
16					
17					
18	7.82				Υ
19					
20	7.89				Y
21					
22					
23					
24					
25	7.96	*			Y
26					
27					
28					
29					
30					
31					
lo = N	l = Exc	ursion	) Tota	l N's	Ø

< <have< td=""><td>County: Columbia Agency: COLUMBIA COUNTY</td></have<>	County: Columbia Agency: COLUMBIA COUNTY				
minimums been met for this day?	ENTRY POINT				
	EP-A				
	PWS ID 4194717				
	COLUMBIA RIVER PUD				
Sample pe	eriod: 3/25 Month/Year				

## Number of excursions during this month: \_\_\_\_\_\_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Nererence	
Minimum Water Quality Parameter(s) as set by State:	
pH 7.2	
Print Name: Gray Hollis	
Signature: Brugaret Hollis	
Date & Phone#: 4/2/25 503.396.05	29

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/