

Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

Day	рΗ	Alk	Phos	Other	Y/N	< <have< th=""><th>County:</th><th>Josephine Agency: JOSEPHINE COUNTY</th></have<>	County:	Josephine Agency: JOSEPHINE COUNTY	
1	7.4				Y	minimum	1		
2						been me	for		
3						this day?		EP-A	
4							PWS	ID 4194765	
5			ļ			BECKLIN HOLDINGS INC			
6									
7						San	ple period:	<u>Е В Ru ARY / 2021</u> Month/Year	
8	7,4				Y	oun		Month/Year	
9									
10						Numbe	Number of excursions during this month:		
11						(Over 9 excursions in 6 months is a violation.			
12						Entry F	Entry Point and Distribution excursions are		
13						cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.			
14	76				17				
15 16	7,5				1	set by	ie State.		
17									
	ļ						Reference		
18 19									
20						/		n Water Quality	
21					+		Paramet	er(s) as set by State:	
22	7.4			-			pH 7	7.3	
23	17				×		- Internet	And a second sec	
24									
25									
26			-			ė.			
27								<u> </u>	
28						, F	int Name: <u> </u>	Jilliam LA BARGE	
29	1		-			S	gnature: <u> </u>	Illim to By	
30			-					2-22-21 541-476-88;	
31						S	end to DWP w	ithin 10 days after end of	
No = N = Excursion) <b>Total N's</b>									
						J Daram PO			

DHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/