

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Josephine Agency: JOSEPHINE COUNTY</th></have<>	County: Josephine Agency: JOSEPHINE COUNTY	
1	7.5				y	minimums	ENTRY POINT	
2		***********				been met for this day?	EP-A	
3	5					uns day?		
5						PWS ID 4194765 BECKLIN HOLDINGS INC		
6								
7							aA. $A$	
8	7,5				Y	Sample period: MARCh / 2021  Month/Year		
9					-			
10						Number of excursions during this month:		
11						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum		
12								
13								
14								
15 16	7.5				Y	set by the Sta	ne.	
17	<u> </u>							
18						Refere	ence	
19					<del> </del>		Minimum Mateu Ouglite	
20							Minimum Water Quality Parameter(s) as set by State:	
21						•		
22	7.6	<del></del>			Y	) 	pH 7.3	
23								
24								
25								
26	<u> </u>							
27	-	-				Print N	ame: William La Bargs	
28	7~				11	Signatı	ure: William Ja Bur e	
30	7,5		-		1	Date &	Phone#: March/29/2021 541-476887	
31						Send to DWP within 10 days after end of		
(No = N = Excursion) Total N's O								
( - <del>-</del> -	/	.541010	11/106	ai in S	<u></u>	]		

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/