

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2 3 4 5 6					
3					
4					
5	7,5				Y
6					-
7					
8					
9					
10					
11					
12	7,5				Y
13					
14					
15					
16					
17					
18					
19					
20					
21	7,6				Y
22					
23					
24					PESSAIR N
25					
26	7,4				Y
27					
28					
29					
30					
31					

< <have< th=""><th colspan="3">County: Josephine Agency: JOSEPHINE COUNTY  ENTRY POINT</th></have<>	County: Josephine Agency: JOSEPHINE COUNTY  ENTRY POINT		
been met for this day?	EP-A		
	PWS ID 4194765		
В	ECKLIN HOLDINGS INC		
Sample pe	riod: April/2021 Month/Year		

Number of excursions during this month: \_\_\_\_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH7.3
Print Name: William La Barre
Signature: Walkin fally
Date & Phone#: 4/26/21 541-476-8871
Send to DWP within 10 days after end of sampling period
19

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/