

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

	/ pH	Alk	Phos	Other	Y/N
1	7,5				Y
2					
3					
4		Sec. Company			
5					
6					
7	7.6				V
8					
9					
10					
11					A2 1000 1
12					Contraction of the Contraction o
13					
14	7.5				V
15					
16					_
17					
18					
19					
20					
21	7.5				Y
22					_
23					
24		Ale			
25					
26					
27					
28	7.5				P
29					
30					
31					

<<Have minimums been met for this day?

County: Josephine Agency: JOSEPHINE COUNTY

## **ENTRY POINT**

EP-A

PWS ID 4194765 BECKLIN HOLDINGS INC

Sample period: June

Number of excursions during this month: \_\_\_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minir Parar	num Water Q neter(s) as se	uality et by State
рН	7.3	

Print Name: /////// Signature: Walley Ja / Date & Phone#: <u>Type 28/2021 541-476-887/</u>

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/