

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th></th><th>County Issorbine Asset ISSES WIT CO.</th></have<>		County Issorbine Asset ISSES WIT CO.	
1						minimur		County: Josephine Agency: JOSEPHINE COUNTY ENTRY POINT	
2						been m		ENTRY POINT	
3						this day	?	EP-A	
4								PWS ID 4194765	
5							В	BECKLIN HOLDINGS INC	
6	7,5				Y				
7						C-		wind, T1 /2221	
8						Sa	mpie pe	eriod: Tuly 2021	
9								WOTHITY Year	
10						Numb	er of ex	cursions during this month:	
11									
12	7.6				Y	(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are			
13								An 'excursion' is any day in which the	
14						water quality parameter(s) fall below the minimum set by the State.			
15									
16									
17			- Machillania				Refere	nce	
18							7 (0/0/0	7700	
19	7.5				Y		N	Minimum Water Quality	
20								Parameter(s) as set by State:	
21									
22	Proposed Acres							pH 7.3	
23									
24									
25					and the second				
26	7.4				Y				
27				1			Drint N	amos falilland 10	
28								ame: William LABARGE	
29								re: Willing Party	
30								Phone#: 7-16-21541-476-88	
31							Send to	DWP within 10 days after end of	
(No =	N = Ex	cursio	n) Tota	al Nic			samplin	g period	

-21541-476-8871 ithin 10 days after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/