

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	/ pH	Alk	Phos	Other	Y/N	
1						< <have minimur<="" td=""></have>
2						been me
3						this day
4						
5						
6						
7	7.4				Y	
8					-	Sar
9						
10						Nursele
11	-					Numbe
12						(Over 9
13	7.5				V	Entry F
14	10					cumula water q
15						set by t
16						
17						
18						
19						
20	7.5				V	
21						
22						
23				-		
24						
25						
26						
27	7.5				7	
28						Pı
29						Si
30						Da
31					-	Se
0 = N	= Excu	rsion) *	Total	N's	8	sa
			_			

< <have minimums been met for</have 	County: Josephine Agency: JOSEPHINE COUNTY ENTRY POINT				
this day?	EP-A				
PWS ID 4194765					
BECKLIN HOLDINGS INC					
Sample pe	riod: <u>September 2021</u> Month/Year				

Number of excursions during this month: ____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.3
Print Name: <u>William La Barge</u>
Signature: Willam R fa Bay
Date & Phone#: 9-27-21 541-476-8871
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/