

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N			
1						< <have minimums<="" td=""><td>County: Josephine Agency: JOSEPHINE COUNTY</td></have>	County: Josephine Agency: JOSEPHINE COUNTY	
2						been met for	ENTRY POINT	
3						this day?	$\mathbf{EP-A}$	
4	7.5				Y		PWS ID 4194765	
5								
6						В	ECKLIN HOLDINGS INC	
7						0		
8						Sample period: OctoB=R/2621 Month/Year		
9								
10	- 00					Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are		
11	7.3				Y			
12								
14						curnulative). A	n 'excursion' is any day in which the	
15						water quality parameter(s) fall below the minimum		
16						set by the State	Э.	
17								
18	7.4				1/	Reference		
19	49				Y			
20						Mi	inimum Water Quality	
21						Pa	rameter(s) as set by State:	
22							oH 7.3	
23					***************************************			
24								
25	7,5				1			
26								
27								
28						Print Name: h////am La Bange		
29						Signature	: William For Byc	
30						Date & Pr	none#: 10/25/21 541-476-8871	
31						Send to D	WP within 10 days after end of	
0 = N :	= Excu	rsion) ⁻	Γotal	N's	2	sampling p	periog	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/