

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Da	у рН	Alk	Phos	Other	Y/N	< <have< th=""><th></th></have<>		
1	7.4				Y	minimums	County: Josephine Agency: JOSEPHINE COUNTY	
2						been met for	ENTRY POINT	
3						this day?	EP-A	
4							PWS ID 4194765	
5						BECKLIN HOLDINGS INC		
6 7								
8	716				T/	Sample pe	riod: Nourmahan /2021	
9	7,4				Y	Sample period: <u>November</u> 2021 Month/Year		
10								
11						Number of excursions during this month:		
12						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are		
13								
14						water quality n	n 'excursion' is any day in which th	
15	7.5				V	water quality parameter(s) fall below the minimum set by the State.		
16					/			
17						Reference		
18						r coreren		
19						M	inimum Water Quality	
20 21						Pa	arameter(s) as set by State:	
22	7 -				7		pH 7.3	
23	7.5				<u>Y</u>			
24								
25				1				
26								
27						l		
28						Print Nan	The second secon	
29	7.5				V	- Contra for the		
30							none#: <u>///29/2021 541-476-8</u>	
31						Send to DWP within 10 days after end of		
D = N	I = Excu	irsion) '	Total	N's	3	sampling	period	
					Prog	ram, PO Box 143	50 Portland OP 07202 0250	

Phone (971) 673-0405 Website: http://healthoregon.org/dwp/