

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	
1						< <have minimums<="" td=""></have>
2						been met
3						this day?
4						
5						
6	7.5				V	
7						
8						Sam
9						
10						Murala
11						Number
12						(Over 9 e
13	7.6				V	Entry Po
14					/_	cumulativ water qu
15						set by the
16						
17						,
18						R
19						
20	7.5				V	
21						
22						
23						
24						
25						
26						
27						
28	7.5			1	7	Prir
29						Sign
30						Date
31						Sen
N = c	= Excu	rsion)	Total	N'e	8	sam

< <have< th=""><th>County: Josephine Agency: JOSEPHINE COUNTY</th></have<>	County: Josephine Agency: JOSEPHINE COUNTY					
minimums been met for	ENTRY POINT					
this day?	EP-A					
PWS ID 4194765						
BECKLIN HOLDINGS INC						
Sample period: <u>December / 2021</u> Month/Year						

Number of excursions during this month: ____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH _ 7.3 _
Print Name: William La BAR git
Signature: Wyling La Box
Date & Phone#: 12/28/21 541-476-8871
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/