

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3 4					
5					
6					
7	7.5				V
8					_/
9					
10					
11					
12					
13					
14	7.6				Y
15	,				
16					
17					
18					
19					
20					
21	7.5				Y
22					/
23					
24					
25					
26					
27					
28	7.5				Y
29					
30					
31					
0 = N	= Exc	ursion)	Total	N's /	3

<<Have minimums been met for this day?

County: Josephine Agency: JOSEPHINE COUNTY

ENTRY POINT

EP-A

PWS ID 4194765 BECKLIN HOLDINGS INC

Sample period: FEBRUARY / 2022

Number of excursions during this month: ____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minir Para	num Water Quality meter(s) as set by State:
рН	7.3

Signature: 4) Illing L Date & Phone#: 2-28-22 541-476-8871

Send to DWP within 10 days after end of

sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/