

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	V/NI
1					1/14
2					
4					
	7,5				
6	110				Y
7	_				
8		-		-	
9					
10					
11 12 7					
13	6			/	
14					
15					
16			_	-	_
17					-
18				_	-
19 <i>Z</i> 20	4			y	
21	-	-			
22	-		_		
23					-
24				_	-
25 26					-
27 7,					
28	3	-		V	
29	-	-	-	-	
30		-	-	-	-
31			<del>-</del>		-
(No = N = E	xcursio	n) To	tal N's	R	1
0	HAD	ا ا سان		0	1

<<Have minimums been met for this day?

County: Josephine Agency: JOSEPHINE COUNTY

## **ENTRY POINT**

EP-A

PWS ID 4194765 BECKLIN HOLDINGS INC

Sample period: DECEN

## Number of excursions during this month: \_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minin Parar	num Water Quality neter(s) as set by State:
рН	7.3

Signature: W Date & Phone#:

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/