

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.5				Y
1 2 3 4 5 6 7					
3					
4					
5					
6					
7					
8	7,5				V
9					
10					
11					
12		******************************			
13					
14					
15	7.5				Y
16				***************************************	
17					
18					
19					
20					
21					
22	7,6				Y
23		9			
24					
25					
26					
27					
28					
29					
30	7,5				Y
31					
No = 1	1 = Exc	ursion) Tota	I N's	0

-

County: Josephine Agency: JOSEPHINE COUNTY

ENTRY POINT

EP-A

PWS ID 4194765
BECKLIN HOLDINGS INC

Sample period: MAU 2023

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

			/ater s) as	lity by Sta	ate:
þ	Н	7.3			

Print Name: William LaBange
Signature: William SaBange
Date & Phone#: 5/30/23 541-476-881/
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/